



ACTEW Water  
Murrumbidgee Ecological Monitoring Program  
Burra Creek Geomorphology Update

June 2015



# Executive Summary

This report has been prepared as a component of the Murrumbidgee Ecological Monitoring Program to satisfy the requirements of the Murrumbidgee to Googong Water Transfer – Aquatic Ecology Monitoring Plan (2014), which is a sub-plan of the M2G Operation Environmental Management Plan (OEMP, 2014).

The objective of the report is to monitor for potential impact of the Murrumbidgee to Googong transfer pipeline (M2G) operation on the geomorphology of Burra Creek downstream of the discharge point, as well as the abstraction point on the Murrumbidgee River.

The M2G operation is currently in standby mode which involves operating each of the pumps in a maintenance mode to ensure the system can be put into full operation at short notice. The pumping rate is limited to 49 ML/d which is approximately half the 109 ML/d capacity during full operational mode. While in standby mode, geomorphic monitoring requires annual visual inspections at key sites. Before entering operating mode, surveyed transects and site observations should be undertaken to re-establish and confirm baseline condition.

This report serves as an update to the previous report in April 2014. Updates to some site surveyed transects have been included along with visual inspections at key sites. Updated transects have been overlaid with previous transects for ease of comparison.

Results have not identified any geomorphological changes as a direct result of pumping activities to date. As M2G is currently in standby mode, the pumps are only run for a short period over a total of approximately two days. Therefore any impacts from the continuous operation of M2G cannot be determined at this point in time. The only maintenance run undertaken in 2014 was in November using the small pump only (~20 ML/d).

The site at BUR2C, approximately 10 km downstream of the discharge point, and 400m upstream of London Bridge, has previously been identified as having a high erosion potential. This site has been photographed for comparison with previous assessments and for future reference.

## **Recommendations:**

- 1) An annual walk of Burra Creek from the discharge point to London Bridge should be continued, including photo monitoring points, to characterise any changes occurring as a result of natural flow events and vegetation growth, especially those that could be exacerbated by a continuous discharge from M2G.
- 2) Visual and photographic monitoring of vegetation encroachment and sediment deposition at the outlet pool (upstream of Williamsdale Rd) should be included in annual monitoring for future reference.
- 3) In addition to existing monitoring, put in place a risk register and management plan for erosion of any stream banks within Burra Creek, whether naturally occurring or a result of pump maintenance runs, and potential impacts to downstream river ecology and receiving water.
- 4) A re-survey of all transects should be undertaken before the commencement of continuous pumping operations.
- 5) The dynamics of the sandbar and macrophyte growth occurring at the pool adjacent to the intake structure at Angle Crossing should continue to be monitored.





# Table of contents

1.	Introduction.....	1
2.	Flow events .....	1
3.	Methodology.....	4
3.1	Creek observations and photogrammetry.....	4
3.2	Burra Creek & Murrumbidgee River Geomorphological Surveys.....	4
4.	Observations & Discussion .....	7
4.1	Creek Observations and photogrammetry.....	7
4.2	Creek Surveys .....	12
5.	Conclusions and Recommendations .....	24
6.	References.....	25

# Table index

Table 3.1.	Pre-Commissioning site cross-sections .....	5
Table 3.2	- Post-Commissioning site cross-sections .....	6
Table 4.1	- BUR1 Channel Units .....	12
Table 4.2	- BUR1C Channel Units .....	14
Table 4.3	- BUR2 Channel Units .....	15
Table 4.4	- BUR2A Channel Units.....	17
Table 4.5	- Pool 29 Channel Units .....	19
Table 4.6	- BUR 2C Channel Units .....	20
Table 4.7	- Angle Crossing Channel Units .....	22

# Figure index

Figure 1	- Burra Creek at Weir (410774) Jan 2010 to Jan-2015.....	2
Figure 2	- 410774 Burra Ck 9/12/2010 Event (1 in 70 yr ARI) .....	2
Figure 3	- 410774 Burra Ck 15/10/2010 Event (1 in 5yr ARI) .....	3
Figure 4	- Burra Weir (410774) flow and turbidity data Nov 2014 maintenance.....	10
Figure 5	- Comparison of Sediment Sieve samples.....	11
Figure 6	- BUR1 Channel Units 10/3/2013.....	12
Figure 7	- BUR1 Aerial 9/4/2014 .....	13
Figure 8	- BUR1C Channel Units 10/3/2013 .....	13
Figure 9	- BUR1C Aerial 9/4/2014.....	14

Figure 10 - BUR2 Channel Units 10/3/2013.....	15
Figure 11 - BUR2 Aerial 9/4/2014 .....	16
Figure 12 – BUR2A Channel Units 10/3/2013 .....	17
Figure 13 - BUR2A Aerial 9/4/2014.....	18
Figure 14 – Pool 29 Channel Units 10/3/2013 .....	18
Figure 15 - Pool 29 Aerial 9/4/2014 .....	19
Figure 16 – BUR 2C Channel Units 10/3/2013 .....	20
Figure 17 - BUR2C Aerial 9/4/2014.....	21
Figure 18 - Angle Crossing Channel Units 10/3/2013.....	22
Figure 19 - BUR 1 3D DGPS Model (July 2013).....	51
Figure 20 – BUR1 XS-1.....	52
Figure 21 – BUR1 XS-2.....	53
Figure 22 – BUR1 XS-3.....	54
Figure 23 - Burra 1C 3D DGPS Model (July 2013).....	66
Figure 24 - BUR1C XS-1A .....	67
Figure 25 - BUR1C XS-1B .....	67
Figure 26 - BUR1C XS-2.....	68
Figure 27 - BUR1C XS-3.....	68
Figure 28 - BUR1C XS-4.....	69
Figure 29 - BUR Discharge 3D DGPS Model (July 2013).....	70
Figure 30 - BUR Discharge 3D GPS XS-1 .....	71
Figure 31 - BUR Discharge 3D GPS XS-2.....	71
Figure 32 - BUR Discharge 3D GPS XS-3.....	72
Figure 33 - BUR Discharge 3D GPS XS-4.....	72
Figure 34 - BUR2A Aerial Photograph (2012 NSW SIX MAPS) .....	73
Figure 35 - BUR2A XS-1 _ 2012.....	74
Figure 36 - BUR2A XS-2 _ 2012.....	74
Figure 37 - BUR2A XS-3 _ 2012.....	75
Figure 38 - BUR2A XS-4 _ 2012.....	75
Figure 39 - Burra U/S Pool 50 DGPS 3D Model (July 2013) .....	82
Figure 40 - BUR U/S Pool 50 3D GPS XS-1 .....	83
Figure 41 - BUR U/S Pool 50 XS-1 _ 2012 .....	83
Figure 42 - BUR U/S Pool 50 3D GPS XS-2.....	84
Figure 43 - BUR U/S Pool 50 XS-2 _ 2012 .....	84
Figure 44 - BUR U/S Pool 50 3D GPS XS-3.....	85
Figure 45 - BUR U/S Pool 50 XS-3 _ 2012 .....	85

Figure 46 - BUR2C Aerial Photo (2012 NSW SIX Maps).....	86
Figure 47 - BUR2C DGPS 3D Model (July 2013) .....	87
Figure 48 - Angle Crossing Aerial Photo (2012 NSW SIX Maps) .....	105
Figure 49 - Angle Crossing D/S DGPS Model (Jan 2013) .....	106
Figure 50 - Angle Crossing DGPS Model Jan 2014.....	107
Figure 51 - Angle Crossing Intake Pool 2015 .....	108
Figure 52 - Angle Crossing U/S 2010 - XS 1 .....	109
Figure 53 - Angle Crossing U/S 2010 - XS 2 .....	109
Figure 54 - Angle Crossing Cross Section at U/S Corner of Inlet Structure .....	110
Figure 55 - Angle Crossing D/S - XS 3 .....	110
Figure 56 - Angle Crossing D/S - XS 4 .....	111
Figure 57 - Angle Crossing D/S 3D GPS XS-1, Jan 2013 .....	111
Figure 58 - Angle Crossing D/S 3D GPS XS-2, Jan 2013 .....	112

# Photo Index

Photo 1 - High erosion potential area downstream of Pool 5 during July (left) and August (right) 2012.....	8
Photo 2 - High erosion potential area downstream of Pool 5 during September (left) and October (right) 2012.....	8
Photo 3 - Erosion potential area downstream of Pool 5 during October 2013 (Left) and January 2014 (Right) .....	9
Photo 4 - Erosion potential area downstream of Pool 5 control in June 2014 (left) and September 2014 (right) –new erosion above gravel layer in embankment.....	9
Photo 5 – Pool 5 left hand side bank starting to erode out above the gravel/boulder layer (September 2014).....	9
Photo 6 - BUR1 24/10/2009 .....	55
Photo 7 - BUR1 9/12/2010 .....	55
Photo 8 - BUR1 9/12/2010 .....	56
Photo 9 - BUR1 17/12/2010 .....	56
Photo 10 - BUR1 26/11/2011 .....	57
Photo 11 - BUR1 1/3/2012 .....	57
Photo 12 - BUR1 8/3/2012 .....	58
Photo 13 - BUR1 20/11/2012 .....	58
Photo 14 - BUR1 24/1/2013 .....	59
Photo 15 - BUR1 17/9/2013 .....	59
Photo 16 - BUR1 19/9/2013 .....	60
Photo 17 - BUR1 15/10/2013 .....	60
Photo 18 - BUR1 12/12/2013 .....	61
Photo 19 - BUR1 17/3/2014 .....	61
Photo 20 - BUR1 17/4/2014 .....	62
Photo 21 - BUR1 26/5/2014 .....	62
Photo 22 - BUR1 25/7/2014 .....	63
Photo 23 - BUR1 15/9/2014 .....	63
Photo 24 - BUR1 19/12/2014 .....	64
Photo 25 - BUR1 4/2/2015 .....	64
Photo 26 - BUR1 15/5/2015 .....	65
Photo 27 - BUR2A 14/2/2012 .....	76
Photo 28 - BUR2A 8/3/2012.....	76
Photo 29 - BUR2A 5/7/2012.....	77
Photo 30 - BUR2A 13/7/2012.....	77
Photo 31 - BUR2A 10/9/2012.....	78

Photo 32 - BUR2A 22/11/2012.....	78
Photo 33 - BUR2A 24/1/2013.....	79
Photo 34 - BUR2A 13/1/2014.....	79
Photo 35 - BUR2A 5/6/2014.....	80
Photo 36 - BUR2A 4/11/2014.....	80
Photo 37 - BUR2A 18/5/2015.....	81
Photo 38 – BUR2C 22/10/2009.....	92
Photo 39 - BUR2C 22/10/2009.....	92
Photo 40 - BUR2C 3/8/2011.....	93
Photo 41 - BUR2C 3/8/2011.....	93
Photo 42- BUR2C 20/3/2012.....	94
Photo 43 - BUR2C 20/3/2012.....	94
Photo 44 - BUR2C 5/7/2012.....	95
Photo 45 - BUR2C 13/7/2012.....	95
Photo 46 - BUR2C 13/7/2012.....	96
Photo 47 - BUR2C 13/7/2012.....	96
Photo 48 - BUR2C 3/9/2012.....	97
Photo 49 - BUR2C 10/9/2012.....	97
Photo 50 - BUR2C 3/10/2012.....	98
Photo 51 - BUR2C 18/10/2012.....	98
Photo 52 - BUR2C 23/1/2013.....	99
Photo 53 - BUR2C 23/1/2013.....	99
Photo 54 - BUR2C 29/4/2013.....	100
Photo 55 - BUR2C 30/10/2013.....	100
Photo 56 - BUR2C 30/10/2013.....	101
Photo 57 - BUR2C 30/10/2013.....	101
Photo 58 - BUR2C 30/10/2013.....	102
Photo 59 - BUR2C 13/1/2014.....	102
Photo 60 - BUR2C 13/1/2014.....	103
Photo 61 - BUR2C 6/6/2014.....	103
Photo 62 - BUR2C 4/9/2014.....	104
Photo 63 - BUR2C 18/5/2015.....	104



# Appendices

Appendix A Creek Maps

Appendix B - Pre Commissioning Pool & Riffle Photos

Appendix C – Post Commissioning Photos (19-21 March 2013): Key Sites

Appendix D – Burra Creek Photos (5-6 June 2014): Key Sites

Appendix E - Sieve Analysis Results

Appendix F - BUR 1: Site Survey

Appendix G - BUR 1C: Site Survey

Appendix H - BUR 2 (Discharge Location): Site Survey

Appendix I - BUR 2A: Site Survey

Appendix J - BUR U/S Pool 50: Site Survey

Appendix K - BUR 2C: Site Survey

Appendix L - Angle Crossing – Site Survey

# 1. Introduction

Icon Water has undertaken the Murrumbidgee to Googong Water Transfer (M2G) project as a means of increasing future water security for the Australian Capital Territory (ACT) and surrounding region. The transfer involves the pumping of up to 109 ML/day from the Murrumbidgee River at Angle Crossing (southern border of the ACT) via a 12 km long buried pipeline discharging into Burra Creek (immediately upstream of Williamsdale Road) that flows to Googong Reservoir via run of river.

This report provides an update to the Geomorphologic Monitoring components of the Murrumbidgee Ecological Monitoring Program (MEMP).

The M2G pipeline construction was completed in August 2012 at which time the commissioning phase was undertaken over an approximate one month period. During that time the various pumps were tested which provided various flow rates up to full capacity.

An initial geomorphic assessment of Burra Creek was undertaken in June 2009 during the approval phase of the M2G project which focused on describing the conditions of Burra Creek and Angle Crossing on the Murrumbidgee River at that time.

The geomorphic assessment was updated in the report issued in April 2014 'Burra Creek geomorphology and vegetation assessment', which contains cross sections and 3D mapping conducted in 2012 and 2013.

This report serves as an update to what has previously been reported to assess whether any changes have occurred in Burra Creek since April 2014. A full geomorphology assessment was not required as the M2G pipeline is currently in standby mode.

While only a visual inspection is required under the revised Geomorphology Monitoring Program (Aquatic Ecology Management Plan, 2014), there have been updates to transects at some of the key sites. Updated transects have been overlaid with previous transects for ease of comparison and can be found in Appendices F to L for those sites.

# 2. Flow events

Historically there have been several significant storm events which have had an influencing factor upon the geomorphology of the creek and the catchment as a whole.

A plot of Burra Creek flow from 2010 to 2015 is shown in Figure 1 (log scale in ML/d shown). The most significant storm event occurred on 9 December 2010, which was approximately a 1 in 70 year Average Recurrence Interval event (Figure 2). This event occurred at the end of the drought following two smaller events (1 in 2 year to 1 in 5 year ARI events) and dramatically altered the geomorphology of the creek through the large scale removal of macrophyte beds and sediment movement which had built up over many years (see Figure 3 for the October 2010 event). Note that these large events still only lasted for a few hours with the flow remaining above 100ML/d for only a day.

Since the December 2010 event there have been 7 events that have exceeded the 1 in 1 year ARI discharge level (~1000 ML/d); once each in 2011, 2013, 2014 and 2015, and three times in 2012. Three of the events were ~3000 ML/d (two in 2012 and one in 2013), and the remaining 4 events were between approximately 1000 ML/d and 1500 ML/d.

Since the previous report in April 2014, there has only been one event at the 1 in 1 year ARI level in early April 2015.

Period 6 Year Plot Start 00:00\_01/01/2010  
 Interval 3 Day Plot End 00:00\_01/01/2016

2010-16




Figure 1 - Burra Creek at Weir (410774) Jan 2010 to Jan-2015

Geomorphological impact from a 1 in 1 year ARI event significantly dominates any impact by a flow of 100 ML/d which represents a natural recurrence interval of less than once in 3 months on average.

The significance of any impact on stream morphology or vegetation created by pumping is most likely to be dictated by the duration of the pumping if it exceeds 2 to 3 weeks.

Period 3 Day Plot Start 00:00\_08/12/2010  
 Interval 6 Minute Plot End 00:00\_11/12/2010

2010




Figure 2 - 410774 Burra Ck 9/12/2010 Event (1 in 70 yr ARI)

Period 2 Day Plot Start 00:00\_15/10/2010  
Interval 4 Minute Plot End 00:00\_17/10/2010

2010




Figure 3 - 410774 Burra Ck 15/10/2010 Event (1 in 5yr ARI)

## 3. Methodology

The methodology used in this report is based on the Aquatic Ecology Management Plan (2014) of the M2G Operation Environment Management Plan (OEMP, 2014). Monitoring has been modified due to the change in operational expectation of the M2G pipeline to reflect that only maintenance pumping is occurring.

It was expected that once the pipeline was commissioned that water transfer would commence almost immediately. However, due to the large increase in ACT Water Supply storage from 2010 to 2012, and maintained level through to 2014, the need for water transfer in the near future from the Murrumbidgee River is now very unlikely. During the period following the commissioning until now there have been regular events of sufficient volume to keep Googong Reservoir volume well above the pumping threshold of 80%, being at or near the 100% full supply level.

A reduced sampling frequency during the current standby period of maintenance is understood to be as follows:

- Annual visual inspections (by a geomorphologist or suitably qualified hydraulic engineer) at key sites, being upstream and downstream of the abstraction and discharge points.
- Prior to the pipeline commencing in Operating mode for continuous water transfer to improve Googong water storage capacity, surveyed transects and site observations should be undertaken to re-establish and confirm baseline condition.
- Annual reporting to ACTEW (Icon Water)

Due to Googong Reservoir currently being at full supply level there is no requirement to operate the M2G pipeline in continuous mode.

### 3.1 Creek observations and photogrammetry

Prior to the initial commissioning phase, the length of Burra Creek was walked from the M2G discharge structure downstream to London Bridge. This was done to evaluate the areas of potential bank erosion and riffle zone adjustment during the operation of the M2G pipeline. This initial walk was completed in July 2012. Photos were taken along the length of the creek of pools and riffle zones for future reference for a comparison of change over time, which can be found in Appendix B. Pools were identified by the numbers given to them in the original geomorphic assessment (ACTEW, 2009).

All riffle zones were given an adjustment potential rating of high, moderate or low, while banks were assessed for erosion potential on each side of the creek individually and given an erosion potential of high, moderate or low. These assessments are consistent with the method employed in the previous geomorphic assessment completed during the EIS phase of the M2G project (ACTEW, 2009).

Follow up walks of Burra Creek were undertaken on 19<sup>th</sup>-21<sup>st</sup> March 2013 and 5<sup>th</sup>-6<sup>th</sup> June 2014 to provide follow up assessment of the condition of key sites which were identified on the pre-commissioning walk, which can be found in Appendices C and D.

### 3.2 Burra Creek & Murrumbidgee River Geomorphological Surveys

Pre-commissioning surveys were undertaken upstream and downstream of the intake structure on the Murrumbidgee as well as along the length of Burra Creek, upstream and downstream of the outlet structure at Williamsdale Rd. The number of sections surveyed is recorded in Table 3.1 with survey dates. The two sites (D/S Pool 51 & D/S Pool 29) were surveyed after being identified as having a riffle zone adjustment potential of moderate during the walk of Burra Creek given in section 2.1.



Table 3.1. Pre-Commissioning site cross-sections

Site	Number of Survey Sections	Date Surveyed
BUR1	3	10/7/2012
BUR1C	5	6/7/2012
BUR2	3	1/8/2012
BUR2A	4	9/7/2012
D/S Pool 51	3	2/8/2012
D/S Pool 29	2	2/8/2012
BUR2C	4	5/7/2012
MUR18	2	10/1/2010
MUR19	2	10/1/2010

Survey sections pre-commissioning of M2G were measured using a dumpy level and graduated staff, where height measurements were recorded at distance intervals across each transect. GPS co-ordinates were collected for the beginning and end points for each transect, and pegged to readily return to transect locations for later surveys. Transect locations were chosen with specific reference to potential erosion and/or scour points at each site.

Survey sections post-commissioning of M2G were undertaken using a differential GPS unit (DGPS) or using the Dumpy level where necessary (some sites have limited DGPS signal acquisition). At some sites both DGPS and Dumpy were used post-commissioning to ascertain the accuracy and validity of the DGPS method.

The stated accuracy of the DGPS is generally indicated as  $\pm 15\text{mm}$  horizontally, and  $\pm 20\text{mm}$  vertically. This accuracy is dependent on the real time kinetic correction factor as received from the closest CORSNET repeater via an internet link.

The number of post-commissioning survey sections undertaken are recorded in Table 3.2 with indicative dates of surveys.

Cross-sections for each site can be found in Appendices F- L overlaid with previous sections where possible to show relative change in the geomorphology at each transect.

Table 3.2 - Post-Commissioning site cross-sections

Location	Number of Survey Sections	Date Surveyed
BUR1	6	2013, 17/6/2014
BUR1c	5	17/6/2014
BUR2	4	Jul-2013
BUR2A	4	6/1/2015
D/S Pool 51	3	Jul-2013
D/S Pool 29	0	n/a
BUR2C	5	30/8/13, 6/1/2015
MUR18	5	April 2013 Jan 2014, 9/1/2015
MUR19	4	Jan 2013, 18/5/2015

## 4. Observations & Discussion

### 4.1 Creek Observations and photogrammetry

The creek observations were undertaken by walking the creek from the M2G discharge point to the London Bridge karst formation. This provided assessments of the riffle zone adjustment potential and the bank erosion potential. The assessments from the observations are presented on the maps found in Appendix A.

#### 4.1.1 Sediment erosion observations

There were nine areas which showed moderate potential for adjustment. The remaining riffle zones were all assessed as having a low adjustment potential. Photos of pools were taken for future comparisons of pool movement and size changes under altered flow conditions and are presented in Appendix B. Subsequent photos of key sites on Burra Creek are shown in Appendix C and Appendix D.

There was potential for a small step (assessed as moderate) located immediately downstream of Williamsdale Road to be adjusted as a result of continuous increased flows from pumping. Plate 1 shows this section of creek at a flow of < 5 ML/d and at 109 ML/d. This step has recently heavily re-vegetated as flows have not been high enough to scour the channel.



Plate 1. Step with moderate adjustment potential immediately downstream of Williamsdale Road, left at < 5 ML/d, right at 100 ML/d

In its current condition, flow from the M2G discharge is unlikely to create erosion of the central channel section. Sediment bars are unlikely to be eroded by normal pumping flows. This may change with further adjustments to the system from natural large events.

#### 4.1.2 Bank erosion assessments

The bank area at Pool 5, immediately upstream of the BUR2C macroinvertebrate sampling site, continues to show the highest potential for substantial erosion. This bank area has been made vulnerable by the high flow events which have scoured the bank and undercut sections over time. Photos of the bank in 2012 are shown in Photo 1 to Photo 2, indicating erosion potential along the bottom of the bank which will increase the undercutting of the bank, resulting in bank collapse into the creek. Photo 3 and Photo 4 show the state of the bank in September 2014.



Photo 1 - High erosion potential area downstream of Pool 5 during July (left) and August (right) 2012



Photo 2 - High erosion potential area downstream of Pool 5 during September (left) and October (right) 2012





Photo 3 - Erosion potential area downstream of Pool 5 during October 2013 (Left) and January 2014 (Right)



Photo 4 - Erosion potential area downstream of Pool 5 control in June 2014 (left) and September 2014 (right)  
 –new erosion above gravel layer in embankment



Photo 5 – Pool 5 left hand side bank starting to erode out above the gravel/boulder layer (September 2014)

The bank immediately upstream of the location shown in Photos 4 and 5 has also started to collapse in sections and eroded significantly since 2009 (refer to photos in Appendix K- BUR 2C: Site Survey).

The other bank areas along Burra Creek assessed as having a high erosion potential would also be vulnerable to a continued elevated flow from the M2G transfer, however not to the same extent. Natural events have a much larger impact potential on the geomorphology than the pump maintenance releases from M2G. However, with the pumps potentially running for a prolonged period (greater than 1 week), this may have additional impact due to increased saturation of the creek embankment and a sustained flow velocity..



### 4.1.3 Sediment Transport & Deposition

With the pipeline in standby mode updated sediment samples have not been taken.

Previous sediment samples in 2013 of the sand bars from BUR2 and BUR2C show that the majority of sediment being deposited within stream is between 0.5 and 2mm in size as seen in Figure 5. This size corresponds to coarse sand. The sample taken from Angle Crossing has a majority of sediment in the 0.25-1mm range, which corresponds to medium and coarse sand.

Individual sieve analysis results can be found in Appendix E. The sediment analysis indicates that the very fine sediments are being transported through to Googong Reservoir in major and minor events and not captured within Burra Creek. The base of the pool at BUR2C contained minimal sediment as it has been eroded to bedrock. Most of the fine sediment along this flatter section of Burra Creek has also been transported downstream into Googong Reservoir, with only a fine covering over the streambed remaining. This sediment is silt/clay as it is predominately below sand size (<63µm).

Sediment transport during maintenance events shows a first flush effect, with a peak followed by a rapid decrease in turbidity as fine particulate matter is moved. Figure 4 below shows level, discharge and turbidity during a maintenance run in November 2014. The hydrograph shows that pumps were in operation during the 6<sup>th</sup>, 7<sup>th</sup>, 11<sup>th</sup>, 12<sup>th</sup> and 13<sup>th</sup> of the month. The initial pumping produced a sharp peak in turbidity which rapidly reduced as the cleaner Murrumbidgee water flowed through the system. When the pumps were switched on again on the 11<sup>th</sup> and 12<sup>th</sup> the turbidity peaks were far lower as fine material had already been transported during the initial pump event on the 6<sup>th</sup>.

In contrast we can see that a minor natural event on the 16<sup>th</sup> produced a large turbidity spike in comparison with the discharge, as a result of sediment entering the waterway from rainfall runoff.




Figure 4 - Burra Weir (410774) flow and turbidity data Nov 2014 maintenance

### Comparison of Sediment Samples




Figure 5 - Comparison of Sediment Sieve samples

## 4.2 Creek Surveys

Creek surveys were undertaken on Burra Creek (2 upstream, 2 downstream) and Angle Crossing (upstream, at the, intake structure and downstream at bend). Surveys included transects, and 3D DGPS for the pool area near the intake..

### 4.2.1 Channel Units

The channel units present at each location are shown below. Channel units have not changed since the previous report but are indicated below for reference.




Figure 6 - BUR1 Channel Units 10/3/2013

Table 4.1 - BUR1 Channel Units



Identifier	Fluvial Environment	Comments
1 	Sand Bar	Sand/gravel
2 	Sand Bar	Sand/cobble
	Ephemeral Channel	Minor Run/Riffle/Pools





Figure 7 - BUR1 Aerial 9/4/2014



Figure 8 - BUR1C Channel Units 10/3/2013



Table 4.2 - BUR1C Channel Units



Identifier	Fluvial Environment	Comments
1 	Sand Bar	Sand/gravel
	Ephemeral Channel	Minor Run/Riffle



Figure 9 - BUR1C Aerial 9/4/2014






Figure 10 - BUR2 Channel Units 10/3/2013

Table 4.3 - BUR2 Channel Units





Identifier	Fluvial Environment	Comments
	Channel	Minor Run
	Pool	
	Step	Approximately 30cm
	Creek Crossing	Pipe Culvert Crossing Multiple 600mm diameter culverts



Figure 11 - BUR2 Aerial 9/4/2014





Figure 12 – BUR2A Channel Units 10/3/2013

Table 4.4 – BUR2A Channel Units



Identifier	Fluvial Environment	Comments
	Channel	Run/Riffle
	Pool	





Figure 13 - BUR2A Aerial 9/4/2014



Figure 14 - Pool 29 Channel Units 10/3/2013

Table 4.5 - Pool 29 Channel Units



Identifier	Fluvial Environment	Comments
	Channel	Run/Riffle
	Pool	



Figure 15 - Pool 29 Aerial 9/4/2014





Figure 16 – BUR 2C Channel Units 10/3/2013

Table 4.6 – BUR 2C Channel Units





Identifier	Fluvial Environment	Comments
	Channel	Run/Riffle
	Pool	
	Crossing	Cobble
	Sand Bar/Deposit	Sand/Gravel







Figure 17 - BUR2C Aerial 9/4/2014





Figure 18 - Angle Crossing Channel Units 10/3/2013

Table 4.7 - Angle Crossing Channel Units

Identifier	Fluvial Environment	Comments
	Channel	Run
	Pool	
	Causeway	Cement
	Major Riffle	Cobble

#### 4.2.2 Survey Transects

Surveys of the Murrumbidgee and Burra site locations are in Appendices as follows:

- Appendix F – BUR1
- Appendix G – BUR1C
- Appendix H – BUR2
- Appendix I – BUR2A
- Appendix J – Pool 50
- Appendix K – BUR2C
- Appendix L – Angle Crossing



There have been a few noticeable changes in some of the cross-sections since the April 2014 report.

Key observations are:

- There has been removal of bank and channel material at BUR1 which has shifted the position of the central channel, due to the September 2013 event (from site visits undertaken afterwards, see Photo 14 to Photo 16).
- There has been continued undercutting and removal of bank material at BUR2C, cross-section 2 on the outside of the bend.
- Deep channel on the left hand side of the Murrumbidgee (looking downstream) opposite the intake structure has had material deposited in it.
- Sand bar in the middle of the pool near the intake structure has had material removed, flattening the sand bar.
- Depth of water adjacent to the intake structure has remained largely unchanged at approximately 0.5m - 0.7m deep during baseflow conditions.
- Cross-sections at the bend downstream of Angle Crossing (XS-3 & 4) show that the central channel profile has become significantly deeper and wider as the sand bar has been washed out.

For more detailed notes on site cross-sections refer to respective appendices.

The natural shifting of the sand bar occurring at the pool adjacent to the intake structure at Angle Crossing has the potential to interfere with pumping activities. It is possible that shifting of the sandbar could create undesirable increased sediment at the intake structure, causing high levels of sediment material to enter the structure placing a heavy load on screen cleaning and sediment removal equipment.

It is also possible that should the water depth adjacent to the intake structure remain at depths less than 700mm as a result of low flows, significant submerged macrophyte growth could occur, which may also obstruct the intake grates and interfere with pumping operations.

## 5. Conclusions and Recommendations

From the pump maintenance run, there was no observed erosion from the banks as a direct result of M2G discharge flows. There was also no evidence that flows initiated any channel or riffle zone adjustment, and no movement of sediment deposits except for remobilisation of very fine sediment that temporarily increased turbidity.

Pool 5 above BUR 2C has previously been identified as having a high erosion potential, and continues to erode from natural flows. When M2G is in operation, it is very likely that prolonged flows around 100ML/d will exacerbate the natural erosion occurring along the base of the western embankment.

To date it has not been possible to monitor Burra Creek during long term pumping rates at approximately 100ML/d.

The sandbar at the intake structure is dynamic and subject to natural shifting which may impact upon the intake structure and water extraction activities. Ongoing shallow water depths at this location could also result in increased submergent macrophyte growth which could interfere with future pumping operations.

### **Recommendations:**

- 1) An annual walk of Burra Creek from the discharge point to London Bridge should be continued, including photo monitoring points, to characterise any changes occurring as a result of natural flow events and vegetation growth, especially those that could be exacerbated by a continuous discharge from M2G.
- 2) Visual and photographic monitoring of vegetation encroachment and sediment deposition at the outlet pool (upstream of Williamsdale Rd) should be included in annual monitoring for future reference.
- 3) In addition to existing monitoring, put in place a risk register and management plan for erosion of any stream banks within Burra Creek, whether naturally occurring or a result of pump maintenance runs, and potential impacts to downstream river ecology and receiving water.
- 4) A re-survey of all transects should be undertaken before the commencement of continuous pumping operations.
- 5) The dynamics of the sandbar and macrophyte growth occurring at the pool adjacent to the intake structure at Angle Crossing should continue to be monitored.

## 6. References




- ACTEW Corporation (2009) *Murrumbidgee to Googong Water Transfer: Environmental Impact Statement*
- ACTEW Corporation (2010a). *Murrumbidgee to Googong Water Transfer. Aquatic Ecology Management Plan.*
- ACTEW Corporation (2010b). *Murrumbidgee to Googong Water Transfer: Geomorphologic Monitoring Sub Plan.*
- ACTEW Corporation (2011). *Murrumbidgee to Googong Water Transfer: Burra Creek Environmental Management Plan.*
- ACTEW Corporation (2012). *Murrumbidgee to Googong Water Transfer: Operation Environmental Management Plan.*
- ACTEW Corporation (2014) *Murrumbidgee to Googong Water Transfer: Operation Environmental Management Plan, Version 2.*
- ACTEW Corporation (2014) *Murrumbidgee to Googong Water Transfer: Aquatic Ecology Monitoring Plan*




DRAFT



# Appendices

# Appendix A Creek Maps



-  Numbered Cross Section
-  Burra Creek
-  M2G Discharge Structure





**Burra Creek Cross Sections:  
BUR 1 & BUR 1C**

Murrumbidgee Ecological Monitoring Program  
ACTEW Water

Job Number | 23-14302  
Revision | A  
Date | 01 May 2013







- Numbered Cross Section
- Burra Creek
- M2G Discharge Structure





**Burra Creek Cross Sections:  
BUR 2 & BUR 2A**  
Murrumbidgee Ecological Monitoring Program  
ACTEW Water

Job Number	23-14302
Revision	A
Date	01 May 2013





 Numbered Cross Section

 Burra Creek



**Burra Creek Cross Sections:  
BUR 2C**

Murrumbidgee Ecological Monitoring Program  
ACTEW Water

Job Number	23-14302
Revision	A
Date	01 May 2013





# Appendix B - Pre Commissioning Pool & Riffle Photos

Pool photos were taken on the 24<sup>th</sup> and 25<sup>th</sup> July 2012 when the average daily flow at Burra weir (gauging station 410774) was 7.9 and 7.8 ML/day respectively. Pool numbering is consistent with that of the previous geomorphic assessment completed during the EIS phase of the M2G project for ease when comparing changes over time.



Pool 1



Pool 2



Pool 3



Pool 4



Pool 5



Pool 6





Pool 7



Pool 8



Pool 9



Pool 10



Pool 11



Pool 12



Pool 13



Pool 14






Pool 15



Pool 16



Pool 17



Pool 18



Pool 19



Pool 20



Pool 21



Pool 22





Pool 23



Pool 24



Pool 25



Pool 26



Pool 27



Pool 28



Pool 29



Pool 30





Pool 31



Pool 32



Pool 33



Pool 34



Pool 35



Pool 36



Pool 37



Pool 38






Pool 39



Pool 40



Pool 41



Pool 42




Pool 43



Pool 44



Pool 45



Pool 46






Pool 47



Pool 48



Pool 49



Pool 50



Pool 51



Pool 52



Pool 53



Pool 54





Pool 55



Pool 56



Pool 57



Pool 58



Pool 59



Pool 60



Pool 61



Pool 62





Pool 63



Pool 64



Pool 65



Pool 66



Pool 67



Pool 68



Pool 69



Pool 70





Pool 71

DRAFT



# Appendix C – Post Commissioning Photos (19-21 March 2013): Key Sites



Step D/S Williamsdale Rd Looking U/S



BUR2A Riffle Looking D/S



BUR2A Riffle Looking U/S



Middle of Riffle U/S Pool 50 Looking U/S



Bottom of Riffle U/S Pool 50





Pool 28 Looking U/S



Pool 28 Looking D/S



Bend U/S BUR2C Riffle

There was no visually detectable change at sites except for the embankment at bend U/S BUR2C riffle where erosion had occurred.



# Appendix D – Burra Creek Photos (5-6 June 2014): Key Sites



U/S of Step, D/S Williamsdale Rd looking D/S



BUR2A Riffle looking D/S



Riffle U/S Pool 50 looking U/S



Riffle U/S Pool 28



Pool 28 Looking D/S



Bank U/S Bend at BUR2C





Bend U/S BUR2C Riffle

DRAFT



## Appendix E - Sieve Analysis Results

Sediment Sieve Analysis


Sample ID: BUR2 - Williamsdale Rd Sand Bar

Sample Date: 30/10/2013

Container Weight 83.2

	Sieve Size (mm)	Weight w/Container (g)	Weight (g)	% Sample (by Wt)	%Passed	Additional Comments
Medium Gravel/Cobble	16	0	0	0.00%	100.00%	
Medium Gravel	8	0	0	0.00%	100.00%	
Fine Gravel	4	88.12	4.92	0.67%	99.33%	
Fine Gravel	2	168.11	84.91	11.56%	87.77%	
Coarse Sand	1	541.41	458.21	62.38%	25.39%	
Coarse Sand	0.5	250.51	167.31	22.78%	2.61%	
Medium Sand	0.25	90.9	7.7	1.05%	1.57%	
Fine Sand	0.125	88.28	5.08	0.69%	0.87%	
Fine Sand	0.063	88.23	5.03	0.68%	0.19%	
Coarse Silt	0.032	84.59	1.39	0.19%	0.00%	
	Total Weight (g)		734.55	100.00%		

**BUR2 - Williamsdale Rd Sand Bar 30/10/2013**



Sediment Sieve Analysis


Sample ID: BUR2C - Sand Bar Opposite Point U/S of Riffle

Sample Date: 29/10/2013

Container Weight 83.2

	Sieve Size (mm)	Weight w/Container (g)	Weight (g)	% Sample (by Wt)	%Passed	Additional Comments
Medium Gravel/Cobble	16		0	0.00%	100.00%	
Medium Gravel	8		0	0.00%	100.00%	
Fine Gravel	4		0	0.00%	100.00%	
Fine Gravel	2	139.2	56	11.24%	88.76%	
Coarse Sand	1		0	0.00%	88.76%	
Coarse Sand	0.5	441.2	358	71.89%	16.87%	
Medium Sand	0.25	153.2	70	14.06%	2.81%	
Fine Sand	0.125	92.2	9	1.81%	1.00%	
Fine Sand	0.063	86.2	3	0.60%	0.40%	
Coarse Silt	0.032	85.2	2	0.40%	0.00%	
Total Weight (g)			498	100.00%		

BUR2C - Sand Bar Opposite Point U/S of Riffle 29/10/2013



Sediment Sieve Analysis


Sample ID: BUR2C - Bend US 2C Riffle - Recent Deposit

Sample Date: 29/10/2013

Container Weight 83.2

	Sieve Size (mm)	Weight w/Container (g)	Weight (g)	% Sample (by Wt)	%Passed	Additional Comments
Medium Gravel/Cobble	16		0	0.00%	100.00%	
Medium Gravel	8		0	0.00%	100.00%	
Fine Gravel	4	86.2	3	0.61%	99.39%	
Fine Gravel	2	105.2	22	4.48%	94.91%	
Coarse Sand	1		0	0.00%	94.91%	
Coarse Sand	0.5	514.2	431	87.78%	7.13%	
Medium Sand	0.25	101.2	18	3.67%	3.46%	
Fine Sand	0.125	92.2	9	1.83%	1.63%	
Fine Sand	0.063	88.2	5	1.02%	0.61%	
Coarse Silt	0.032	86.2	3	0.61%	0.00%	
	Total Weight (g)		491	100.00%		

BUR2C - Bend US 2C Riffle - Recent Deposit 29/10/2013





Sediment Sieve Analysis


Sample ID: BUR2C - Island Bar Off Point

Sample Date: 30/10/2013

Container Weight 83.2

	Sieve Size (mm)	Weight w/Container (g)	Weight (g)	% Sample (by Wt)	%Passed	Additional Comments
Medium Gravel/Cobble	16		0	0.00%	100.00%	
Medium Gravel	8		0	0.00%	100.00%	
Fine Gravel	4	89	5.8	1.31%	98.69%	
Fine Gravel	2	120.7	37.5	8.49%	90.20%	
Coarse Sand	1	278.1	194.9	44.12%	46.08%	
Coarse Sand	0.5	226.87	143.67	32.52%	13.56%	
Medium Sand	0.25	120.5	37.3	8.44%	5.11%	
Fine Sand	0.125	98.09	14.89	3.37%	1.74%	
Fine Sand	0.063	88.09	4.89	1.11%	0.63%	
Coarse Silt	0.032	86	2.8	0.63%	0.00%	
	Total Weight (g)		441.75	100.00%		

**BUR2C - Island Bar Off Point 30/10/2013**



Sediment Sieve Analysis


Sample ID: BUR2C - Sand Bar US Causeway

Sample Date: 30/10/2013

Container Weight 83.2

	Sieve Size (mm)	Weight w/Container (g)	Weight (g)	% Sample (by Wt)	%Passed	Additional Comments
Medium Gravel/Cobble	16		0	0.00%	100.00%	
Medium Gravel	8		0	0.00%	100.00%	
Fine Gravel	4	332.05	248.85	24.65%	75.35%	
Fine Gravel	2	212.51	129.31	12.81%	62.54%	
Coarse Sand	1	438.71	355.51	35.21%	27.33%	
Coarse Sand	0.5	299.26	216.06	21.40%	5.93%	
Medium Sand	0.25	131.73	48.53	4.81%	1.12%	
Fine Sand	0.125	91.58	8.38	0.83%	0.29%	
Fine Sand	0.063	85.13	1.93	0.19%	0.10%	
Coarse Silt	0.032	84.23	1.03	0.10%	0.00%	
	Total Weight (g)		1009.6	100.00%		

BUR2C - Sand Bar US Causeway 30/10/2013



Sediment Sieve Analysis


Sample ID: BUR2C - Adjacent Collapsed Bank US Riffle

Sample Date: 30/10/2013

Container Weight 83.2

	Sieve Size (mm)	Weight w/Container (g)	Weight (g)	% Sample (by Wt)	%Passed	Additional Comments
Medium Gravel/Cobble	16		0	0.00%	100.00%	
Medium Gravel	8		0	0.00%	100.00%	
Fine Gravel	4	87.3	4.1	0.65%	99.35%	
Fine Gravel	2	131	47.8	7.62%	91.73%	
Coarse Sand	1	466.5	383.3	61.06%	30.67%	
Coarse Sand	0.5	264.1	180.9	28.82%	1.85%	
Medium Sand	0.25	93.05	9.85	1.57%	0.28%	
Fine Sand	0.125	84.4	1.2	0.19%	0.09%	
Fine Sand	0.063	83.75	0.55	0.09%	0.00%	
Coarse Silt	0.032		0	0.00%	0.00%	
Total Weight (g)			627.7	100.00%		

BUR2C - Adjacent Collapsed Bank US Riffle 30/10/2013





Sediment Sieve Analysis


Sample ID: BUR2C - Point Bar Opposite Bend (South Bank)

Sample Date: 30/10/2013

Container Weight 83.2

	Sieve Size (mm)	Weight w/Container (g)	Weight (g)	% Sample (by Wt)	%Passed	Additional Comments
Medium Gravel/Cobble	16		0	0.00%	100.00%	
Medium Gravel	8		0	0.00%	100.00%	
Fine Gravel	4	85.2	2	0.44%	99.56%	
Fine Gravel	2	119.8	36.6	7.97%	91.60%	
Coarse Sand	1		0	0.00%	91.60%	
Coarse Sand	0.5	465.2	382	83.17%	8.43%	
Medium Sand	0.25	110.2	27	5.88%	2.55%	
Fine Sand	0.125	90	6.8	1.48%	1.07%	
Fine Sand	0.063	86.6	3.4	0.74%	0.33%	
Coarse Silt	0.032	84.7	1.5	0.33%	0.00%	
	Total Weight (g)		459.3	100.00%		

BUR2C - Point Bar Opposite Bend (South Bank) 30/10/2013



Sediment Sieve Analysis


Sample ID: Angle Crossing US Causeway (Beach)

Sample Date: 30/10/2013

Container Weight: 83.2

	Sieve Size (mm)	Weight w/Container (g)	Weight (g)	% Sample (by Wt)	%Passed	Additional Comments
Medium Gravel/Cobble	16	0	0	0.00%	100.00%	
Medium Gravel	8	0	0	0.00%	100.00%	
Fine Gravel	4	83.88	0.68	0.08%	99.92%	
Fine Gravel	2	85.81	2.61	0.31%	99.61%	
Coarse Sand	1	120.1	36.9	4.38%	95.23%	
Coarse Sand	0.5	457.25	374.05	44.41%	50.82%	
Medium Sand	0.25	492.57	409.37	48.60%	2.22%	
Fine Sand	0.125	100.81	17.61	2.09%	0.12%	
Fine Sand	0.063	84.18	0.98	0.12%	0.01%	
Coarse Silt	0.032	83.27	0.07	0.01%	0.00%	
Total Weight (g)			842.27	100.00%		

Angle Crossing US Causeway (Beach) 30/10/2013



# Appendix F - BUR 1: Site Survey




Figure 19 - BUR 1 3D DGPS Model (July 2013)

Section	Bank Side*	2012		3D Model	
		Latitude	Longitude	Latitude	Longitude
<u>1</u>	LHS	35.59797 S	149.22783 E	35.59799 S	149.22784 E
	RHS	35.59758 S	149.2277 E	35.59759 S	149.22771 E
<u>2</u>	LHS	35.59797 S	149.22777 E	35.59773 S	149.22777 E
	RHS	35.59768 S	149.22758 E	35.59767 S	149.22759 E
<u>3</u>	LHS	35.59803 S	149.22755 E	35.59806 S	149.22754 E
	RHS	35.59785 S	149.22728 E	35.59783 S	149.22728 E

\* As seen looking Downstream (flow direction is top right to bottom left in 3D model, LHS closest to section numbers)






Figure 20 - BUR1 XS-1

- The 2013 cross section taken using a DGPS unit (Red) closely matches the cross section recorded by dumpy in 2012(Blue)
- The 2014 cross section closely matches previous sections except for in the bottom of the channel, which shows widening of the channel.

## Cross-Section




Figure 21 - BUR1 XS-2

- The 2013 cross section taken using the DGPS unit (Red) closely matches the cross section recorded by dumpy in 2012 (Blue)
- Difference at CH16-20m due to flood debris that has moved or eroded away. Peak point ~CH19m on top of log.
- The 2014 cross section closely matches on the left hand side, however the right hand side shows some erosion to the bank. Some of the difference is due to the sheer vertical bank making it difficult to take sections exactly up the same part of the bank as previously, actual material removal from the bank is ~1m.
- Left hand side of the channel at chainage 30m, which is on the inside of the bend, shows deposition of material from high flows.

## Cross-Section




Figure 22 - BUR1 XS-3

- The 2013 cross section taken using the DGPS unit (Red) closely matches the 2012 cross section recorded by dumpy (Blue)
- Some erosion from top of bank at ~CH29m
- Spike at ~CH15m difference due to flood debris, top of branch.
- The 2014 cross section closely matches the 2013 section, however the central channel has shifted from chainage 22m to 18m, and become deeper and more defined.




Photo	Comment
 <p data-bbox="165 1055 552 1084">Photo 6 - BUR1 24/10/2009</p>	<ul style="list-style-type: none"> <li>- First photo on record for BUR1</li> <li>- Evidence of erosion outside of bend.</li> <li>- Stable vegetation on 60%-80% of visible stream banks.</li> <li>- Sediment deposits within channel.</li> <li>- Creek channel dry.</li> </ul>
 <p data-bbox="165 1957 536 1986">Photo 7 - BUR1 9/12/2010</p>	<ul style="list-style-type: none"> <li>- DS of BUR1 sample area at Cassidy's Crk confluence.</li> <li>- Turbid Burra Creek flowing left to right bottom of photo.</li> <li>- Less suspended material entering through Cassidy's Ck, due to less bank erosion and highly vegetated channel.</li> </ul>



Photo	Comment
 <p data-bbox="165 972 536 999">Photo 8 - BUR1 9/12/2010</p>	<ul style="list-style-type: none"> <li data-bbox="1241 181 1503 315">- Tail end of severe flood event. Peak of event went over the RHS bank.</li> <li data-bbox="1241 331 1503 383">- Scouring of banks and channel</li> <li data-bbox="1241 398 1503 450">- Vegetation removal</li> <li data-bbox="1241 465 1503 600">- Highly turbid water indicates significant sediment transport.</li> <li data-bbox="1241 616 1503 750">- Heavy debris load deposited by flood waters including tree on RHS bank.</li> </ul>
 <p data-bbox="165 1653 536 1680">Photo 9 - BUR1 17/12/2010</p>	<ul style="list-style-type: none"> <li data-bbox="1241 1061 1503 1218">- About a week after event. Evidence of bank undercutting as result of flood waters.</li> <li data-bbox="1241 1234 1503 1413">- Large riparian vegetation removed with significant new debris and sediment deposited.</li> <li data-bbox="1241 1451 1503 1503">- Banks unstable after vegetation removal.</li> </ul>



Photo	Comment
 <p data-bbox="165 882 568 913">Photo 10 - BUR1 26/11/2011</p>	<ul style="list-style-type: none"> <li data-bbox="1241 181 1508 264">- Grass re-established on banks</li> <li data-bbox="1241 271 1508 353">- Native Shrubs re-establishing in riparian zone.</li> </ul>
 <p data-bbox="165 1765 536 1796">Photo 11 - BUR1 1/3/2012</p>	<ul style="list-style-type: none"> <li data-bbox="1241 974 1476 1005">- High flow event</li> <li data-bbox="1241 1012 1497 1095">- High turbidity from native reserve upstream</li> </ul>





Photo	Comment
 <p data-bbox="167 963 534 996">Photo 12 - BUR1 8/3/2012</p>	<ul style="list-style-type: none"> <li data-bbox="1244 179 1500 291">- Evidence of additional bank erosion on outside of bend</li> <li data-bbox="1244 302 1500 414">- Bankside grass vegetation on LHS flattened by previous flow.</li> </ul>
 <p data-bbox="167 1836 534 1870">Photo 13 - BUR1 20/11/2012</p>	<ul style="list-style-type: none"> <li data-bbox="1244 1019 1500 1131">- Bank shows signs of minor erosion from October '12 event</li> <li data-bbox="1244 1142 1500 1310">- Bankside vegetation recovered And growing strongly after decent rainfall</li> </ul>







Photo	Comment
 <p data-bbox="165 965 552 994">Photo 14 - BUR1 24/1/2013</p>	<ul data-bbox="1241 181 1509 479" style="list-style-type: none"> <li>• Summer die off of grasses</li> <li>• Increased vegetation recovery from previous year</li> <li>• Surface flow has ceased but sub surface remains moist</li> </ul>
 <p data-bbox="165 1749 552 1778">Photo 15 - BUR1 17/9/2013</p>	<ul data-bbox="1241 1025 1509 1106" style="list-style-type: none"> <li>- 3000 MI/d event (1 in 3yr ARI)</li> <li>-</li> </ul>



Photo	Comment
 <p data-bbox="165 880 552 909">Photo 16 - BUR1 19/9/2013</p>	<ul style="list-style-type: none"> <li>- Significant removal of material from right hand bank from large event.</li> </ul>
 <p data-bbox="165 1760 552 1792">Photo 17 - BUR1 15/10/2013</p>	<ul style="list-style-type: none"> <li>- Right hand side bank collapse and deposition of material on outside of bend.</li> <li>- Majority of bankside vegetation retained through event.</li> </ul>



Photo

Comment



- Strong vegetation growth after rain and warm weather.

Photo 18 - BUR1 12/12/2013



- Dry conditions causing grass die off.

Photo 19 - BUR1 17/3/2014



Photo	Comment
 <p data-bbox="165 965 552 992">Photo 20 - BUR1 17/4/2014</p>	<ul style="list-style-type: none"> <li>- Following two events &gt; 1 in 3 month ARI vegetation is showing signs of growth.</li> </ul>
 <p data-bbox="165 1845 552 1872">Photo 21 - BUR1 26/5/2014</p>	



Photo

Comment



Photo 22 - BUR1 25/7/2014



Photo 23 - BUR1 15/9/2014



Photo	Comment
 <p data-bbox="165 969 571 1003">Photo 24 - BUR1 19/12/2014</p>	<ul style="list-style-type: none"> <li data-bbox="1236 138 1519 293">- Evidence of channel shift and bank erosion following event in previous week.</li> <li data-bbox="1236 293 1519 465">- Vegetation growth on left hand side bank has spread, stabilising more of the bank.</li> </ul>
 <p data-bbox="165 1854 536 1888">Photo 25 - BUR1 4/2/2015</p>	<ul style="list-style-type: none"> <li data-bbox="1236 1019 1519 1093">- Evidence of further bank collapse</li> </ul>



Photo

Comment



- Little change, evidence of some weathering on right hand side bank

Photo 26 - BUR1 15/5/2015

DRAFT

# Appendix G - BUR 1C: Site Survey




Figure 23 - Burra 1C 3D DGPS Model (July 2013)

Section	Bank Side*	2012		3D Model	
		Latitude	Longitude	Latitude	Longitude
<u>1</u>	LHS	35.55682 S	149.221 E	35.55682 S	149.22099 E
	RHS	35.55682 S	149.22112 E	35.55679 S	149.22111 E
<u>2</u>	LHS	35.5565 S	149.2211 E	35.55650 S	149.22110 E
	RHS	35.55653 S	149.22122 E	35.55653 S	149.22122 E
<u>3</u>	LHS	35.55633 S	149.22117 E	35.55633 S	149.22117 E
	RHS	35.55637 S	149.22128 E	35.55637 S	149.22128 E
<u>4</u>	LHS	35.55623 S	149.22118 E	35.55623 S	149.22118 E
	RHS	35.55627 S	149.22093 E	35.55627 S	149.22130 E


\* As seen looking downstream (flow direction bottom left to top right in 3D image)

DGPS Survey equipment experiencing signal difficulties at this site, resulting in DGPS cross-sections not matching dumpy sections.



Cross-Section

Comment



- XS-1B lies perpendicular to the channel while XS-1A starts at the same point but runs at an angle to the channel to a different end point DS..
- Cross Sections from 2012 and 2014 closely match, differences due to slightly different line taken over/through vegetation.

Figure 24 - BUR1C XS-1A




Figure 25 - BUR1C XS-1B

Cross-Section

Comment




Figure 26 - BUR1C XS-2

- 2012 and 2014 cross sections closely match, differences due to variations in vegetation growth.
- There has been some deepening of the central channel at chainage 6m.





Figure 27 - BUR1C XS-3

- 2012 and 2014 cross sections closely match, marker pegs could not be found in 2012 for exact points, survey in 2014 was made using GPS coordinates. Minor differences due to vegetation.

Cross-Section

Comment



- Resurvey of cross section with DGPS required to complete/append to DGPS model
- 2012 and 2014 cross sections closely match, minor differences due to vegetation.

Figure 28 - BUR1C XS-4

DRAFT



# Appendix H - BUR 2 (Discharge Location): Site Survey




Figure 29 - BUR Discharge 3D DGPS Model (July 2013)

		3D Model	
Section	Bank Side*	Latitude	Longitude
1	LHS	35.55585 S	149.22228 E
	RHS	35.55601 S	149.22233 E
2	LHS	35.55589 S	149.22243 E
	RHS	35.55602 S	149.22248 E
3	LHS	35.55585 S	149.22247 E
	RHS	35.55602 S	149.22257 E
4	LHS	35.55582 S	149.22256 E
	RHS	35.55597 S	149.22264 E

\* As seen looking downstream (flow direction from bottom right to top left in 3D image)

Cross-Section	Comments
---------------	----------




Figure 30 - BUR Discharge 3D GPS XS-1




Figure 31 - BUR Discharge 3D GPS XS-2

Cross-Section

Comments




Figure 32 - BUR Discharge 3D GPS XS-3




Figure 33 - BUR Discharge 3D GPS XS-4



# Appendix I - BUR 2A: Site Survey



Figure 34 - BUR2A Aerial Photograph (2012 NSW SIX MAPS)

Section	Bank Side*	2012	
		Latitude	Longitude
<u>1</u>	LHS	35.55372 S	149.22492 E
	RHS	35.55382 S	149.22525 E
<u>2</u>	LHS	35.55362 S	149.22512 E
	RHS	35.55373 S	149.22528 E
<u>3</u>	LHS	35.55357 S	149.22513 E
	RHS	35.55353 S	149.22528 E
<u>4</u>	LHS	35.55348 S	149.22517 E
	RHS	35.55343 S	149.22527 E




Figure 35 - BUR2A XS-1 \_ 2012

- There is little difference between the pre and post commissioning cross sections.
- Variation in sections from ~8m to ~17m due to summer macrophyte growth in channel





Figure 36 - BUR2A XS-2 \_ 2012


- No observable difference between pre and post commissioning sections
- Left hand side peg had been knocked out and was repositioned due to wombat activity.

Cross-Section

Comments



- No significant difference between pre and post commissioning sections.
- RHS peg was knocked out and slightly repositioned.



- No notable difference between pre and post commissioning surveys.
- Variations between sections at ~11m due to a rock that was not picked up in 2012.

Figure 38 - BUR2A XS-4\_2012



Photo	Comments
 <p data-bbox="183 990 593 1025">Photo 27 - BUR2A 14/2/2012</p>	<ul style="list-style-type: none"> <li>- Looking upstream</li> <li>- Stable riparian vegetation present</li> </ul>
 <p data-bbox="183 1796 577 1832">Photo 28 - BUR2A 8/3/2012</p>	<ul style="list-style-type: none"> <li>- Flow event ~ 100 ML/d</li> <li>- Evidence of higher waters pushing vegetation over</li> <li>- No evidence of erosion</li> </ul>







Photo	Comments
 <p data-bbox="183 985 574 1019">Photo 29 - BUR2A 5/7/2012</p>	<ul style="list-style-type: none"> <li>- Normal water levels</li> <li>- Evidence of vegetation die off during winter months for emergent macrophytes</li> </ul>
 <p data-bbox="183 1877 590 1910">Photo 30 - BUR2A 13/7/2012</p>	<ul style="list-style-type: none"> <li>- Med flow event - ~110ML/d</li> </ul>



Photo	Comments
 <p data-bbox="183 974 598 1008">Photo 31 - BUR2A 10/9/2012</p>	<ul style="list-style-type: none"> <li data-bbox="1260 145 1508 414">- Med flow event (This includes an M2G pump maintenance run ~20ML/d +~5ML/d baseflow)</li> <li data-bbox="1260 425 1508 571">- No evidence of new bank erosion from pumped flow</li> <li data-bbox="1260 582 1508 627">- Turbidity low</li> </ul>
 <p data-bbox="183 1859 614 1892">Photo 32 - BUR2A 22/11/2012</p>	



Photo

Comments



- Noticeable increase in reed growth along left side of stream

Photo 33 - BUR2A 24/1/2013



- Bank has remained stable

Photo 34 - BUR2A 13/1/2014





Photo 35 - BUR2A 5/6/2014



Photo 36 - BUR2A 4/11/2014

- Vegetation growth on banks has prevented any significant erosion.



Photo

Comments



Photo 37 - BUR2A 18/5/2015

- No evidence of change
- Autumn die-back of vegetation

DRAFT



# Appendix J - BUR U/S Pool 50: Site Survey





Figure 39 - Burra U/S Pool 50 DGPS 3D Model (July 2013)

Section	Bank Side*	2012		3D Model	
		Latitude	Longitude	Latitude	Longitude
<u>1</u>	LHS	35.54125 S	149.22625 E	35.54124 S	149.22626 E
	RHS	35.54123 S	149.22607 E	35.54124 S	149.22600 E
<u>2</u>	LHS	35.54138 S	149.22627 E	35.54139 S	149.22633 E
	RHS	35.5414 S	149.2261 E	35.54140 S	149.22606 E
<u>3</u>	LHS	35.54147 S	149.22628 E	35.54147 S	149.22637 E
	RHS	35.54148 S	149.22615 E	35.54149 S	149.22613 E

\* As seen looking downstream (flow direction from left to right in 3D image)

Cross-Section



Comments

- DGPS survey longer than Dumpy cross section to accommodate 3D profiling
- Original survey pegs could not be found at time of 3D survey.
- Channel sections indicate similar profile, accurate survey needed to re-establish section

Figure 40 - BUR U/S Pool 50 3D GPS XS-1





Figure 41 - BUR U/S Pool 50 XS-1 \_ 2012

Cross-Section

Comments



- DGPS survey longer than Dumpy cross section to accommodate 3D profiling
- Original survey pegs could not be found at time of 3D survey.
- Channel sections indicate similar profile, accurate survey needed to re-establish section

Figure 42 - BUR U/S Pool 50 3D GPS XS-2




Figure 43 - BUR U/S Pool 50 XS-2 \_ 2012



Cross-Section




Figure 44 - BUR U/S Pool 50 3D GPS XS-3




Figure 45 - BUR U/S Pool 50 XS-3 \_ 2012

Comments

- DGPS survey longer than Dumpy cross section to accommodate 3D profiling
- Original survey pegs could not be found at time of 3D survey.
- Channel sections indicate similar profile, accurate survey needed to re-establish section
- Differences due to rock outcrops picked up in ~1m misalignment of cross sections

# Appendix K - BUR 2C: Site Survey



Yellow lines indicate location of cross-sections at BUR2C.

Some original cross-section pegs have moved due to erosion effects or earthwork impact from moving of the creek crossing.

Locations to be confirmed

Section	Bank Side*	2010		2012 & 2013	
		Latitude	Longitude	Latitude	Longitude
<u>D/S – XS4</u>	LHS	35.51774 S	149.26123 E	35.51768 S	149.26128 E
	RHS	35.51758 S	149.26156 E	35.51758 S	149.2615 E
<u>@ Bend – XS3</u>	LHS	35.51808 S	149.26141 E	35.51815 S	149.26148 E
	RHS	35.51835 S	149.26154 E	35.51832 S	149.26157 E
<u>XS2</u>	LHS			35.51816 S	149.26114 E
	RHS			35.51831 S	149.26131 E
<u>@ Old Road Xing – XS1</u>	LHS	35.51880 S	149.26135 E	35.51883 S	149.26125 E
	RHS	35.51867 S	149.26154 E	35.51862 S	149.2616 E

\* As seen looking downstream (flow direction is bottom to top in the adjacent figure)

▪

Figure 46 - BUR2C Aerial Photo (2012 NSW SIX Maps)






Figure 47 - BUR2C DGPS 3D Model (July 2013)

- In-stream points U/S of Riffle absent due to water level or loss of DGPS correction signal at base of embankment during survey.

DRAFT



### BUR2C - Cross Section 4




D/S Site 2C XS-4

comments

2013 section using DGPS

Cross sections all closely match  
Material in central channel has shifted slightly

# BUR2C - Cross Section 3




U/S 2C @ Bend XS-3

Comments

All sections by Dumpy

Continued erosion from left hand side bank.  
 LHS peg repositioned again.  
 Some reforming of sand bar on right hand side bank at ~13m

## BUR2C - Cross Section 2



BUR2C @ Undercut Bank XS-2


Comments

2013 section using DGPS

Central channel continues to erode the bank on left hand side  
Sand has been eroded on RHS bank at ~10m



# BUR2C - Cross Section 1



U/S @ Old Road Crossing XS-1

Comments

2013 section using DGPS  
 (slight discrepancies in 2013 section at ~1m and ~5m probably due to signal problems under trees on top of bank and signal shadow close to the base of the bank)

Left hand side bank has slumped at the top at ~2m, depositing material closer to the channel at ~5m.  
 Sand bar at ~11m has been eroded away during an event.

Photo	Comments
 <p data-bbox="183 808 616 837">Photo 38 - BUR2C 22/10/2009</p>	<ul style="list-style-type: none"> <li>- Earliest photo on project record for BUR2C</li> <li>- Taken upstream of BUR2C riffle</li> <li>- Some grass coverage on banks</li> </ul>
 <p data-bbox="183 1525 616 1554">Photo 39 - BUR2C 22/10/2009</p>	<ul style="list-style-type: none"> <li>• Region of dense macrophyte growth above BUR2C prior to 2010 events which scoured the whole channel to bedrock</li> </ul>



Photo

Comments



Photo 40 - BUR2C 3/8/2011

- looking upstream at dog-leg upstream of BUR 2C riffle site.
- Bedrock visible in pool with algal growth
- Significant sediment and cobble deposit on inside of bend as a result of December 2010 flood event



Photo 41 - BUR2C 3/8/2011

- Ongoing bank erosion
- Site of XS-3
- High algal growth due to elevated nutrient levels and warmer water temperature as vegetation previously shading the creek was washed out during flood





Photo	Comments
 <p data-bbox="181 987 584 1016">Photo 42- BUR2C 20/3/2012</p>	<ul style="list-style-type: none"> <li data-bbox="1281 152 1506 264">- Evidence of bank erosion caused by flood</li> <li data-bbox="1281 275 1458 353">- Little bank vegetation remaining.</li> <li data-bbox="1281 365 1506 533">- XS-2 located at the downstream end of the eroded embankment</li> <li data-bbox="1281 544 1458 622">- XS-3 in foreground location</li> </ul>
 <p data-bbox="181 1883 584 1912">Photo 43 - BUR2C 20/3/2012</p>	<ul style="list-style-type: none"> <li data-bbox="1281 1048 1506 1160">- Further bank erosion downstream of bend.</li> </ul>



Photo	Comments
 <p data-bbox="181 976 576 1010">Photo 44 - BUR2C 5/7/2012</p>	<ul style="list-style-type: none"> <li data-bbox="1281 152 1501 232">- Entire bank on outside of bend eroding</li> <li data-bbox="1281 241 1501 353">- No vegetation recovery during winter evident</li> </ul>
 <p data-bbox="181 1906 592 1939">Photo 45 - BUR2C 13/7/2012</p>	<ul style="list-style-type: none"> <li data-bbox="1281 1079 1501 1113">- Elevated flows</li> <li data-bbox="1281 1122 1501 1249">- Turbid flows indicate suspended sediment transport</li> </ul>



Photo

Comments



Photo 46 - BUR2C 13/7/2012



Photo 47 - BUR2C 13/7/2012

- Embankment erosion further upstream from BUR2C



Photo

Comments



Photo 48 - BUR2C 3/9/2012



- Sediment deposition evident on outside of bend.



Photo 49 - BUR2C 10/9/2012

- Woody debris present in channel
- Fine Sediment deposit evident
- Eroded banks too steep to allow easy vegetation regrowth for stability



Photo	Comments
 <p data-bbox="181 969 592 1003">Photo 50 - BUR2C 3/10/2012</p>	<ul data-bbox="1299 181 1445 237" style="list-style-type: none"> <li>- Bank collapse</li> </ul>
 <p data-bbox="181 1888 611 1921">Photo 51 - BUR2C 18/10/2012</p>	<ul data-bbox="1299 1070 1509 1182" style="list-style-type: none"> <li>- Sediment deposits in areas of low velocity</li> </ul>



Photo

Comments



- Sloping banks show signs of vegetation recovery
- Vegetation growth commencing on sediment deposits

Photo 52 - BUR2C 23/1/2013



Photo 53 - BUR2C 23/1/2013







Photo	Comments
 <p data-bbox="183 981 593 1012">Photo 54 - BUR2C 29/4/2013</p>	<ul style="list-style-type: none"> <li>- Section of bank has slumped into channel.</li> </ul>
 <p data-bbox="183 1816 609 1848">Photo 55 - BUR2C 30/10/2013</p>	<ul style="list-style-type: none"> <li>- Significant section of embankment scoured after Sept event</li> </ul>



Photo	Comments
 <p data-bbox="181 887 609 918">Photo 56 - BUR2C 30/10/2013</p>	<ul style="list-style-type: none"> <li>- slumping of embankment sections following Sept 2013 storm event</li> </ul>
 <p data-bbox="181 1686 609 1718">Photo 57 - BUR2C 30/10/2013</p>	<ul style="list-style-type: none"> <li>- Bank Scour from Sept event</li> <li>- Reforming of point bar from the event.</li> <li>- Mid and outer bend scoured to bedrock</li> </ul>



Photo

Comments



Photo 58 - BUR2C 30/10/2013

- Movable gravel bed control for Pool 5



Photo 59 - BUR2C 13/1/2014

- Shallow pool over bedrock with no shading riparian vegetation allows for ready growth of filamentous algae



Photo

Comments



Flow beginning to cause significant undercutting of bank.

Photo 60 - BUR2C 13/1/2014



Bank has had minor collapsed from undercutting

Photo 61 - BUR2C 6/6/2014



Photo	Comments
 <p data-bbox="183 837 576 869">Photo 62 - BUR2C 4/9/2014</p>	<ul style="list-style-type: none"> <li data-bbox="1278 152 1500 432">- Erosion at Pool 5 within soft embankment layer has commenced and will cause significant collapse in future</li> </ul>
 <p data-bbox="183 1816 592 1848">Photo 63 - BUR2C 18/5/2015</p>	<ul style="list-style-type: none"> <li data-bbox="1278 954 1508 1122">- No evidence of major geomorphic change at bend from 2013.</li> <li data-bbox="1278 1133 1500 1240">- Increase in macrophyte re-establishment</li> </ul>



## Appendix L - Angle Crossing – Site Survey



Figure 48 - Angle Crossing Aerial Photo (2012 NSW SIX Maps)

Original cross section locations in yellow (10<sup>th</sup> jan 2010). US Cross Section 2 not accessible during M2G construction.




Figure 49 - Angle Crossing D/S DGPS Model (Jan 2013)

\*DGPS Model corresponds to area between the pink cross-sections in previous Figure 48. The change in the downstream sandbar due to the 2010 and 2012 flood events






Figure 50 - Angle Crossing DGPS Model Jan 2014

Cross section shown in Figure 50 corresponds to the upstream corner of the inlet structure. The DGPS model does not cover the full extent of river due to the water level being outside of the range of the DGPS at some locations. This was outside of the designated survey area being near the inlet structure. The raised ridge in green through the centre of the river bathymetry is due to points collected along the concrete causeway.




Figure 51 - Angle Crossing Intake Pool 2015


Sections shown in Figure 51 correspond to U/S cross sections 1 and 2. Left hand side of 3D model is incomplete as the bank cannot be accessed due to dense vegetation growth.

Section	Bank Side*	2010		GPS Model		2013	
		Latitude	Longitude	Latitude	Longitude	Latitude	Longitude
<u>1</u>	LHS	35.58403 S	149.10779 E	35.57947 S	149.11024 E	35.58403 S	149.10779 E
	RHS	35.58423 S	149.10810 E	35.57940 S	149.11107 E	35.58423 S	149.10810 E
<u>2</u>	LHS	35.58343 S	149.10806 E	35.57787 S	149.11017 E		
	RHS	35.58363 S	149.10862 E	35.57781 S	149.11080 E		
<u>3</u>	LHS	35.58092 S	149.11102 E				
	RHS	35.58081 S	149.11136 E				
<u>4</u>	LHS	35.58057 S	149.11091 E				
	RHS	35.58044 S	149.11134 E				



Cross Section

Comments



- Differences due to taking a slightly different line through the rock outcrop
- 2015 section follows closely with line of 2010 survey, river bed in central channel is bedrock.

Figure 52 - Angle Crossing U/S 2010 - XS 1




Figure 53 - Angle Crossing U/S 2010 - XS 2




Figure 54 - Angle Crossing Cross Section at U/S Corner of Inlet Structure

- 2014 and 2015 cross sections do not quite match on slope of inlet grate due to differences in RTK adjustment and slight error induced by whether previous GPS survey on or beside concrete edge.
- All sections have been aligned to top corner of intake structure
- 2015 sections shows that the sand bar in the river has shifted, becoming flatter in the centre, and slightly deeper adjacent to the intake ~Ch.43m.
- Deep channel on left hand side has had ~0.6 m of sand deposited since 2014 survey.




Figure 55 - Angle Crossing D/S - XS 3

- Cross sections were aligned to left hand side (looking downstream) GPS point. Original marker lost.
- Sections adjusted to level at left hand side end point to show relative change in elevation.
- Significant removal of sediment bar in main channel resulting in deep cross-section.
- 2015 cross-section was not completed due to depth and water velocity now present at section. Boat survey required to complete section.






Figure 56 - Angle Crossing D/S - XS 4

- Cross sections were aligned to left hand side (looking downstream) GPS point.
- Sections adjusted to level at left hand side end point to show relative change in elevation.
- Significant removal of sediment bar in channel resulting in deep cross-section.
- 2015 cross-section was not completed due to depth and water velocity now present at section. Boat survey required to complete section.




Figure 57 - Angle Crossing D/S 3D GPS XS-1, Jan 2013




Figure 58 - Angle Crossing D/S 3D GPS XS-2, Jan 2013

- DGPS cross section ends in-stream due to water level and vegetation not allowing access to opposite bank at time of survey





GHD


16 Marcus Clarke St Canberra ACT 2601  
PO Box 1877 Canberra ACT 2601 Australia  
T: 61 2 6113 3200 F: 61 2 6113 3299 E: cbrmail@ghd.com.au

© GHD 2015

This document is and shall remain the property of GHD. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

G:\23\15101\WP\68616.docx

Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
1	D Ainsworth N Mueller	N. Mueller		Norm Mueller		18/06/2015
2	D Ainsworth N Mueller	N. Mueller		Norm Mueller		24/06/2015

[www.ghd.com](http://www.ghd.com)

